

FIG. 1




FIG. 2




FIG. 3A




FIG. 3B




FIG. 4A




FIG. 4B




FIG. 5




FIG. 6A





FIG. 6B



VEHICLE BODY END PORTION

FIG. 7




FIG. 8A




FIG. 8B




FIG. 8C





FIG. 8D








FIG. 10A




FIG. 10B




FIG. 11




FIG. 12




FIG. 13




FIG. 14 RELATED ART




FIG. 15A RELATED ART




FIG. 15B RELATED ART

